

**RECEIVED**  
**CENTRAL FAX CENTER**

MAR 23 2006

# FAX MESSAGE



Commissioner of Patents and Trademarks  
U.S. Patent and Trademark Office

**Bennett Jones LLP**  
1000 ATCO Centre  
10035 - 105 Street  
Edmonton Alberta  
T5J 3T2

Tel 780.917.5231  
Fax 780.421.7951

FAX NO. 571-273-8300

PHONE NO.

DATE March 23, 2006

This is the first page of 12

FROM Edward (Ted) Yoo

LAWYER NO 807 FILE NO 45197.2

Original Status - Retained on File

If all pages not received, call 780.421.8133 for assistance.

This facsimile was successfully transmitted at:

**Message**

Application No.: 09/713,296  
Filing Date: November 16, 2000  
Inventor (first named): Perrault  
Group Art Unit: 3637  
Examiner Name: Phi Dieu N. Tran A  
Attorney Docket No.: 45197.2

Enclosed is an Appeal Brief Under 37 C.F.R. 41.37 In Response to Final Office Action Mailed 08/23/2005 with Credit Card Payment Form attached.

Edward Yoo 41435

U:\allstaff\Eileen\PIUS\FAX\Amendments and Responses.doc THIS MESSAGE IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN INFORMATION THAT IS PRIVILEGED AND CONFIDENTIAL. IF YOU ARE NOT THE INTENDED RECIPIENT, OR THE EMPLOYEE RESPONSIBLE FOR DELIVERING THE MESSAGE TO THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY DISSEMINATION OF THIS COMMUNICATION IS STRICTLY PROHIBITED. IF YOU HAVE RECEIVED THIS COMMUNICATION IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE. THANK YOU.

CALGARY • EDMONTON • TORONTO

**BEST AVAILABLE COPY**

**RECEIVED  
CENTRAL FAX CENTER**

**MAR 23 2006**

**IN THE UNITED STATES PATENT & TRADEMARK OFFICE**

Application No.: 09/713,296  
Filing Date: November 16, 2000  
Inventor (first named): Perrault  
Group Art Unit: 3637  
Examiner Name: Phi Dieu N. Tran A.  
Attorney Docket No.: 45197.2

---

**Certificate of Transmission Under 37 C.F.R. 1.8(a)**

I hereby certify that this document is being facsimile transmitted on this date March 23, 2006 to  
FAX No. 571-273-8300 to the U.S. Patent and Trademark Office, Attention: Examiner Phi Dieu Tran A.  
at Group Art Unit 3637 in Arlington, VA 22202

  
EILEEN LUCAS

DATED: March 23, 2006

---

**APPEAL BRIEF UNDER 37 C.F.R. 41.37  
IN RESPONSE TO FINAL OFFICE ACTION MAILED 08/23/2005**

To: Assistant Commissioner for Patents  
Washington, DC 20231

Sir:

Notice of Appeal was timely filed January 23, 2005, and the following appeal brief is filed within two months of filing the Notice of Appeal.

Applicant is providing an Appeal Brief under 37 C.F.R. 41.37(c)(1), with regard to claims 1-17, 20 and 21.

03/24/2006 MBINAS 00000002 09713296  
01 FC:2402 250.00 OP

**APPEAL BRIEF UNDER 37 C.F.R. 41.37(C)(1)**

Applicant provides Appeal Brief under 37 C.F.R. 41.37(c)(1). The Appeal Brief is filed within the time allowed for Appeal Brief of two months after filing the Notice of Appeal under 37 C.F.R. 41.37(a)(1). The fee for this Appeal Brief is 500.00 under 35 U.S.C. 41(a)(6)(B), which is reduced by half as the applicant claims small entity status under 37 C.F.R. 1.27 for a total of \$250.00. Fee payment by Credit Card form is transmitted herewith.

**(i) Real Party in Interest**

The real parties in interest are the applicants Larry Perrault and David R. Karroll.

**(ii) Related Appeals and Interferences**

There are no prior or other pending appeals, judicial proceedings or interferences known to the appellant which may be related to, directly affect or be directly affected by or have any bearing on the Board's decision in the pending appeal.

**(iii) Status of Claims**

Claims 1-17, 20 and 21 are rejected and under appeal.

Claims 18 and 19 are objected and not under appeal.

**(iv) Status of Amendments**

An amendment to claim 18 dated 01/23/2005, has been filed subsequent to the final rejection mailed 08/23/2005 and has not yet been entered by the examiner.

**(v) Summary of Claimed Subject Matter**

The present invention provides for an improved roof truss. It reduces cracking between the ceiling finish and the interior partition wall finish caused by arching of the roof trusses. This is accomplished by means of a bottom plate which is attached to the bottom chord of the roof truss. The top member of interior partition walls is attached to the bottom plate in such a way that the bottom plate does not lift away from the top plate of the interior walls despite vertical movement of the bottom chord of the roof truss (see page 2, lines 17-22).

According to Figures 1-15, the improved truss (10) of independent claim 1 comprises a bottom chord (12), a top chord and at least two intermediate members creating a triangular shape with one of the top or bottom chords, wherein the improvement comprises: a bottom plate (14) disposed beneath and substantially parallel to the bottom chord (12); and means for attaching the bottom plate to the bottom chord (16) which allows separation of the bottom plate from the bottom chord when the bottom plate is attached to an interior partition wall and the roof truss rises relative to the interior partition wall.



**(vii) Argument**

1. **Whether claims 17, 20-21 are properly rejected under 35 U.S.C. 102(e) as being anticipated by Kost (U.S. Patent 6,047,503).**

The Kost reference teaches pre-manufactured wall frames – there is absolutely no teaching of roof trusses. Kost does not teach any form of roof truss. Examiner referred to Figure 12 and stated that element 23 is equivalent to a bottom chord and that element 2A is equivalent to the bottom plate. Element 23 may be the bottom chord of a roof truss, although it is identified as a cross-beam. However, element 2A is not a bottom plate. It is a top part of the wall framing unit. The difference may be seen in that element 2A in Kost which Examiner has equated to the bottom plate runs perpendicular to the longitudinal axis of the roof truss. In the case of the present invention, the bottom plate is parallel to such axis, because it is part of the truss. The parallel characteristic is a claimed limitation in claims 1 and 17. The present invention is an improved roof truss, which adds the element of a bottom plate, disposed below the bottom chord. This is best seen in Figure 1 of the present invention. It is important to consider that the bottom plate is a separate element from the bottom chord, not part of the bottom chord.

2. **Whether claims 1-5, 7-11 and 13-16 are properly rejected under 35 U.S.C 103(a) as being unpatentable over Laughlin (U.S. Patent 1,444,798) in view of Kost (U.S. Patent 6,047,503).**

With respect, it is submitted that no *prima facie* case of obviousness may be made. Kost does not teach a roof truss, which is the object of the present claims. In particular, neither Laughlin nor Kost does not teach a bottom plate which is parallel to the bottom chord.

3. **Whether claims 1-2 and 6 are properly rejected under 35 U.S.C. 103(a) as being unpatentable over Laughlin (U.S. Patent 1,444,798) in view of Thompson (U.S. Patent 6,094,880).**

First, it is submitted that no *prima facie* case of obviousness may be made. In particular, neither Laughlin nor Thomson teaches a bottom plate which is parallel to the bottom chord of a roof truss.

4. **Whether claim 12 is properly rejected under 35 U.S.C. 103(a) as being unpatentable over Laughlin (U.S. Patent 1,444,798) in view of Kost (U.S. Patent 6,047,503) and further in view of Boozer (U.S. Patent 5,743,063).**

Claim 12 depends from claim 1 and is therefore also submitted to be free of the prior art.

5. **Whether claim 17 is properly rejected under U.S.C. 103(a) as being unpatentable over Laughlin (U.S. Patent 1,444,798) in view of Kost (U.S. Patent 6,047,503).**

It is submitted that no *prima facie* case of obviousness may be made. Neither Laughlin nor Kost teach a bottom plate which is parallel to the bottom chord of a roof truss.

**(viii) Claims Appendix**

Claims involved in this appeal are provided below.

1. (Previously Amended) An improved roof truss comprising a bottom chord, a top chord and at least two intermediate members creating a triangular shape with one of the top or bottom chords, wherein the improvement comprises:
  - a) a bottom plate disposed beneath and substantially parallel to the bottom chord; and
  - b) means for attaching the bottom plate to the bottom chord which allows separation of the bottom plate from the bottom chord when the bottom plate is attached to an interior partition wall and the roof truss rises relative to the interior partition wall.
2. (Original) The improved roof truss of claim 1 wherein the means for attaching the bottom plate to the roof truss comprises a plurality of connectors.
3. (Original) The improved roof truss of claim 2 wherein the connectors are removable.
4. (Original) The improved roof truss of claim 2 wherein the connectors are frangible.
5. (Original) The improved roof truss of claim 1 wherein the means for attaching the bottom plate to the roof truss comprises one or more connectors slidably attached to the bottom plate and the roof truss.
6. (Original) The improved roof truss of claim 2 wherein the connectors are fasteners driven through the bottom plate into the bottom of the bottom chord.

7. (Original) The improved roof truss of claim 2 wherein the connectors are gang plates.
8. (Original) The improved roof truss of claim 2 wherein the connectors comprise a plurality of wood fasteners and hangers having a plurality of holes, wherein the wood fasteners are driven through the holes in the hangers into the bottom plate, the bottom chord or both.
9. (Original) The improved roof truss of claim 8 wherein the hangers are frangible.
10. (Original) The improved roof truss of claim 9 wherein the hangers have a perforation disposed in such a way that if the hanger is severed at the perforation, the hanger and fasteners will no longer act to attach the bottom plate to the bottom chord.
11. (Original) The improved roof truss of claim 8 wherein the hangers are slidably attached to the bottom plate and the bottom chord.
12. (Original) The improved roof truss of claim 11 wherein the holes are vertically slotted holes.
13. (Original) The improved roof truss of claim 8 wherein the hangers are H-shaped hangers.
14. (Original) The improved roof truss of claim 8 wherein the hangers are U-shaped hangers.
15. (Original) The improved roof truss of claim 8 wherein the hangers are wrap-around hangers.
16. (Original) The improved roof truss of claim 8 wherein the hangers are metal.

17. (Previously Amended) An improved roof truss, comprising:
- (a) a bottom chord;
  - (b) a bottom plate disposed underneath and substantially parallel to the bottom chord;
  - (c) means for attaching the bottom plate to the bottom chord; and
  - (d) spacers disposed between the bottom plate and the bottom chord which create a thermal gap between the bottom plate and the bottom chord.
20. (Previously Amended) The improved roof truss of claim 17 further comprising a strap, located at the intersection of the bottom plate and an interior partition wall, said strap passing between the bottom plate and the bottom chord, wherein said strap may be fastened to the interior partition wall wherein fasteners can be driven through the planar member on either side of the bottom plate so as to attach the bottom plate to the interior partition wall.
21. (Original) The improved roof truss of claim 20 wherein the strap is metal.



**(ix) Evidence Appendix**

There has been no evidence submitted under 37 C.F.R. 1.130, 1.131 or 1.132.

Copies of evidence relied upon as grounds of rejection in Final Office Action dated 08/23/2005 are listed below.

1. U.S. Patent 6,047,503 to Kost
2. U.S. Patent 1,444,798 to Laughlin
3. U.S. Patent 6,094,880 to Thompson
4. U.S. Patent 5,743,063 to Boozer


**(x) Related Proceedings Appendix**

None.

10

Respectfully submitted,

Larry Perrault, et al.

By:   
Edward Yoo (Reg. No. 41,435)

CORRESPONDENCE ADDRESS: Customer No. 22828

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS

☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

☐ FADED TEXT OR DRAWING

☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING

☐ SKEWED/SLANTED IMAGES

☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS

☐ GRAY SCALE DOCUMENTS

☐ LINES OR MARKS ON ORIGINAL DOCUMENT

☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**